TAC		TODAYS FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Entries must be endorsed with Name, Rating Technician or Repair Facility. (See back page	g and Certificate Number
01/27/	/2017 6	Dale	A. dastan	Founttoville AD 72701 (470)025 4991	
01/2//	2017, 5	outh Deli	ta Aviation	, Fayetteville, AR. 72701, (479)935-4891	
N46CS,	Cessna	P210N, 9	S/N:P21000	0413, Hobbs: 1735.1, AFTT: 4480.7	
				, INC. Ground run aircraft to ops check gau	ige. Checked normal.
Wilson		74879 <u>-</u>		Wilson	870-572-9011
Wilson	A&P 24	74879 <u>-</u>			
Wilson South N46C Hobb	A&P 24 Delta A	748791 .viation	The :	Helena-West Helena, AR 72390 ELT: 8-2019	870-572-9011 Date: 7-27-17 TTA: 4494.9
South N46C Hobb Comple Checke gear ret	A&P 24 Delta A S s: 1749. eted annual ed ELT in a truction/ext	74879 Sviation 3 inspection to accordance we consion test is	this date: Chec	Helena-West Helena, AR 72390 ELT: 8-2019 cked cables, pulleys, bellcranks, hinges and bearings. Chec (7(d) and installed new battery – next due 8-2019. Jacked a temergency modes – found satisfactory operation in both. R	870-572-9011 Date: 7-27-17 TTA: 4494.9 ked lighting. Serviced hattery, tircraft. Performed landing e-packed main wheel bearings
South N46C Hobb Comple Checke gear ret and rep	A&P 24 Delta A S s: 1749. eted annual ed ELT in a traction/ext	74879 Viation 3 inspection tecordance we ension test is and wheel to	this date: Chec	Helena-West Helena, AR 72390 ELT: 8-2019 cked cables, pulleys, bellcranks, hinges and bearings. Chec 17(d) and installed new battery – next due 8-2019. Jacked a temergency modes – found satisfactory operation in both. R se gear. Tightened right main gear actuator attach bolts. R	870-572-9011 Date: 7-27-17 TTA: 4494.9 ked lighting. Serviced hattery, uircraft. Performed landing e-packed main wheel bearings eplaced bulb in tail nay and
N46C Hobb Comple Checke gear ret and rep repaired AD list aircraft	A&P 24 Delta A S s: 1749. eted annual ed ELT in a traction/ext diaced races d wiring. R in aircraft using Val-	74879 Viation 3 inspection to ecordance we consider the state and wheel I lee-glued edge tecords for a Spar "LIC"	this date: Checouth FAR 91.20 in normal and e bearings on more see of wing boo details of comp polyurethane p	Helena-West Helena, AR 72390 ELT: 8-2019 cked cables, pulleys, bellcranks, hinges and bearings. Chec (7(d) and installed new battery – next due 8-2019. Jacked a temergency modes – found satisfactory operation in both. R	870-572-9011 Date: 7-27-17 TTA: 4494.9 ked lighting. Serviced battery. urcraft. Performed landing e-packed main wheel bearings eplaced bulb in tail nav and ails/rollers - found ok. See n entire aircraft. Painted olors are: Titanium White.

Michael D. Schlesselman A&P34691891A